Paw Paw Fire Station



Construction Update

832 S Gremps St, Paw Paw, MI 49079

Report By: Daniel Burns

Date: 7/22/2022





Recent Progress:

- Started installation of joist bridging and steel decking at Department side
- Completed erection of the Apparatus Bay pre-engineered structure
- Completed Hose Tower masonry
- Started insulation and roof panels at Apparatus Bay
- Continued exterior sheathing at Department and green girt/insulation at Apparatus Bay
- Set hollow metal frames in masonry and steel stud bearing walls
- Completed kitchen underground plumbing rough-ins

Work Scheduled for Next Week:

- Complete Apparatus Bay roof installation
- Continue interior bearing and non-bearing steel stud framing
- Continue green girt and insulation at Apparatus Bay
- Start apparatus bay underground rough-ins


<u>Issues/Items that we are working on:</u>

Building Utilities: AVB awaiting design drawings from Midwest Energy for permanent power system.
 Received design drawings from Consumers Energy for gas service. Coordinating underground sleeving for both services.

Project Budget and Schedule:

- Current Budget through Change Order #04: \$5,520,281

 (This amount does not include approved changes which have not had a change order issued or Bulletins and other changes or which final pricing has not been approved.)
- Current Substantial Completion: November 30, 2022





Description Roof insulation fabric started over mezzanine

Taken Date 07/21/2022 at 01:50 pm

Upload Date 07/21/2022 at 01:53 pm

Uploaded By Aaron Lindsay

File Name A614426A-1AEA-4A8D-8...



Week of 7.18.22

Description Insulated sheathing and decking on Fire Education room.


Taken Date 07/21/2022 at 01:47 pm

Upload Date 07/21/2022 at 01:50 pm

Uploaded By Aaron Lindsay

File Name F58E1B34-CCB2-4808-A...








Description Steel decking installed over Dayroom and Kitchen areas

Taken Date 07/20/2022 at 03:39 pm

Upload Date 07/20/2022 at 03:40 pm

Uploaded By Aaron Lindsay

File Name CFAEC3FE-04E2-42D4-A...



Week of 7.18.22

Description
Z-girt and iso board
installed along north
apparatus bay wall


Taken Date 07/20/2022 at 03:38 pm

Upload Date 07/20/2022 at 03:38 pm

Uploaded By Aaron Lindsay

File Name 173DC518-2841-48EC-B...







Description Roof insulation fabric installation above apparatus bay

Taken Date 07/20/2022 at 03:37 pm

Upload Date 07/20/2022 at 03:37 pm

Uploaded By Aaron Lindsay

File Name 1AC5178E-0D65-4D23-9...



Week of 7.18.22

Description
Department side roofing material delivered to site.
Apparatus bay roofing staged on roof already.


Taken Date 07/20/2022 at 03:36 pm

Upload Date 07/20/2022 at 03:37 pm

Uploaded By Aaron Lindsay

File Name 6BFE6493-76A5-49B9-8...







Description Fabric installation over apparatus bay.

Taken Date 07/19/2022 at 03:33 pm

Upload Date 07/19/2022 at 03:33 pm

Uploaded By Aaron Lindsay

File Name 2A632651-A848-47B3-A...



Week of 7.18.22

Description Joist bridging installation/ welding


Taken Date 07/19/2022 at 03:30 pm

Upload Date 07/19/2022 at 03:30 pm

Uploaded By Aaron Lindsay

File Name 1901D888-2292-43FA-9...







Description
Masonry wall HM window installation in Radio/Sec
Storage room

Taken Date 07/19/2022 at 03:30 pm

Upload Date 07/19/2022 at 03:30 pm

Uploaded By Aaron Lindsay

File Name 1C1C93FA-9951-4960-8...



Week of 7.18.22

Description HM door and window frame installation for Fire Ed. Room west wall


Taken Date 07/19/2022 at 03:27 pm

Upload Date 07/19/2022 at 03:28 pm

Uploaded By Aaron Lindsay

File Name 209753E1-07AD-4C85-8...







Description HM door and window frame delivered to site

Taken Date 07/18/2022 at 03:36 pm

Upload Date 07/18/2022 at 03:37 pm

Uploaded By Aaron Lindsay

File Name 274E24F1-E260-429D-A...

